



CARMAX CERTIFIED INSPECTION REPORT

VEHICLE DETAILS

VIN WBSKG9C56DJ594439 Stock Number 15986335


Year 2013 Make BMW

Model M3 Mileage 62,688

Date Inspected 09/20/2018

Location of Inspection [Store Number, Store Name] 7159, CARMAX - MODESTO

Every car undergoes the following inspection as part of CarMax's certification program. **Certain vehicles may have unrepaired safety recalls. Check www.nhtsa.gov/recalls to learn if this vehicle has an unrepaired safety recall.** This list encompasses the major mechanical systems checked and, if needed or equipped, serviced. However, not all items inspected or serviced are included and additional work may have been performed as needed during the reconditioning process. The CarMax certification program is not affiliated with any original equipment manufacturer (OEM) or other third party. Non-OEM parts may be used, CarMax does not make any representation that this vehicle has never been in an accident or collision.



GENERAL REQUIREMENTS

- AutoCheck® Vehicle History Report (AutoCheck® is accessed on every vehicle and if certain conditions are shown, the vehicle will not be eligible for retail sale)
- Structural Inspection (no structural damage found)
- VIN Inspection (VIN plate on dash is visible; no signs of tampering)
- Flood Inspection (no flood damage found)
- Odometer Inspection (odometer reading in miles; no signs of tampering)

COSMETIC INSPECTION

- Carpet (clean, no excessive wear or damage)
- Floor Mats (clean, no excessive wear or damage)
- Seat Upholstery (clean, no excessive wear or damage)
- Interior Surfaces (clean, no excessive wear or damage)
- Headliner (clean, no excessive wear or damage)
- Exterior Body/Windows (washed and waxed; free of bugs, oil, tar)
- Wheels/Hubcaps (clean, no excessive wear or damage)

Printed 01/03/2019 11:26 am 1 of 1



Reprint #: 1 DMS Tracking #: 1915642

Form Number: PFF2119 Rev. Date: 04/2017

Meets Standards
 Repaired / Replaced
 N/A

Meets Standards
 Repaired / Replaced
 N/A

MECHANICAL INSPECTION

Engine

- Engine Oil and Filter (replaced)
- Engine Air Filter (clean, free of debris)
- Vacuum Hoses & Lines (free of leaks and noises)
- Exhaust System (free of excessive noise, leaks, rust)
- Engine Mounts (free of excessive cracks, rips, tears)
- Oil Leaks (confirm no oil leaks present)
- Engine Belts (free of tears and excessive noise)
- Head Gasket (free of leaks)
- Emission Controls (no check engine light illuminated)
- Electric Drive Motor (operational)

Cooling System

- Radiator Condition (free of leaks and cracks)
- Radiator Cap (free of leaks, holds pressure)
- Radiator Hoses (free of cracks, swelling, leaking)
- Heater Hoses (free of cracks, swelling, leaking)
- Cooling Fan (operational)
- Overflow Tank (free of leaks)
- Water Pump (operational, free of leaks)
- Temperature Gauge (test drive shows operational)

Fuel System

- Fuel Tank (free of perforating rust, leaks)
- Fuel Lines & Hoses (free of cracks, swelling, leaks)
- Fuel Pump (test drive shows correct operation)
- Gas Cap (free of leaks)

Transmission and Drivetrain

- Universal Joints/Drive Shaft (free of tears, bends, leaks, looseness, abnormal sounds and vibrations)
- Axle/Differential (free of tears, bends, leaks, looseness, abnormal sounds and vibrations)
- Transmission Fluid (confirm no transmission fluid leaks present)
- Transmission Mounts (free of excessive cracks, rips, tears)
- Transmission Lines & Hoses (free of cracks, swelling, leaks)
- 4WD/AWD (operates correctly, free of abnormal sounds and vibrations)
- Manual Transmission (shifts correctly, free of abnormal sounds and vibrations)
- Automatic Transmission (shifts correctly, free of abnormal sounds and vibrations)

Steering System

- Tie Rods (free of tears, bends, leaks, looseness, abnormal sounds)
- Steering Gear/Rack & Pinion (free of tears, bends, leaks, looseness, abnormal sounds)
- Steering Linkage (free of bends, looseness, abnormal sounds)
- Power Steering Pump/Motor (free of leaks; steering wheel turns smoothly)
- Steering Hoses, Lines & Wires (free of cracks, swelling, leaks)
- Shaft & Couplings (free of bends, looseness, abnormal sounds)
- Alignment (no excessive pulling; steering wheel centered)

Heating and A/C System

- Compressor/Clutch (free of cracks, leaks, excessive noise)
- Condenser (free of leaks)
- Evaporator (free of leaks)
- AC Hoses & Lines (free of cracks, swelling, leaking)
- Temperature/Blower Control Assembly (temperature, fan speed, vent selection operate correctly)
- Heater Core (no water / coolant leaks visible under dash)
- Rear AC (operates correctly)

Lighting System

- Exterior Lights (operates correctly)
- Brake Light Assembly (free of cracks, excessive moisture; illuminates correctly)
- Turn Signal Lever (illuminates turn signals correctly)
- Interior Lights (operates correctly)
- Hazard Light Button/Switch (illuminates hazard lights correctly)
- Headlights Assembly (free of cracks, excessive moisture; illuminates correctly)
- Rear License Plate Light Assembly (free of cracks, excessive moisture; illuminates correctly)
- Interior Dome Light Assemblies (illuminates dome lights correctly)
- High/Low Beam Indicator (illuminates correctly)
- High/Low Beam Selection Lever (operates correctly)

Meets Standards
Repaired / Replaced
N/A

Meets Standards
Repaired / Replaced
N/A

MECHANICAL INSPECTION CONT

Suspension System

- Ball Joints (free of tears, leaks, looseness, abnormal sounds)
- Springs/Leaf Springs/Torsion Bars (no cracks, excessive noises; appropriate ride height)
- Sway Bar/Links (free of tears, bends, leaks, looseness, abnormal sounds)
- Control Arms/Bushings (free of tears, bends, leaks, looseness, abnormal sounds)
- Rear Shocks/Struts (free of leaks, bends, worn or loose components)
- Front Shocks/Struts (free of leaks, bends, worn or loose components)

Tires and Wheels

- Tire Condition (minimum depth 4/32", no tears, leaks, plugs, excessive cracking, bulges)
- Wheels (free of excessive vibration, bends, cracks)
- Wheel Well Moldings (secured, no excessive damage)

Brake System

- Parking Brake Operation (fully functional; free of leaks, excessive wear on lines, cables, and friction material)
- Parking Brake Indicator Light (illuminates when parking brake is in use)
- Master Cylinder/Booster/Power Brake Assist (road test shows vehicle stops when braking)
- Pedal Brake Operation (free of play, travel is normal)
- Brake Lines/Hoses/Fittings (free of leaks, swelling, cracking)
- Brake Pads/Shoes/Hardware (shoes 2/32" min. thickness; pads 4/32" min. thickness; free of cracks, excessive tapering; clean and lubricated)
- Brake Rotors/Drums (meets OEM min. thickness/ max. diameter; no excessive vibration, free of excessive rust, grooves, pits, hot spots)
- Brake Calipers/Wheel Cylinders (free of leaks and tears, free piston movement, no excessive drag or pull, vehicle stops when braking)
- Anti-Lock Brake System (ABS) (warning indicator light not illuminated; system does not engage in normal driving conditions)

Electrical System

- Ignition System (idles and starts normally)
- Alternator/Regulator (appropriate charging voltage; no visible abnormal wear and tear)
- Starter Operation (engages normally)
- Battery Condition (cases/terminals/leads/wires/ hardware intact; passes load test)

Body / Interior

- Sun Visors (secured and operates correctly)
- Rear View Mirror (secured and operates correctly)
- Hood Latch/Release (operates correctly)
- Trunk or Tailgate (locks and latches operate, secure, and seal correctly)
- Fuel Door Latch/Release (operational)
- Side Windows (operate and seal correctly)
- Side Doors (locks and latches operate, secure, and seal correctly)
- Side Door Hinges (operates smoothly, free of binding/bending)
- Seat Operation (all seat adjustments work correctly; seats secure)
- Headrests (present and operational)
- Audio/Entertainment System (sound and screen operational)
- Speakers (no cracking, tears, distortion)
- Clock (clock set to current time)
- Speedometer and Odometer (proper operation, readout visible, no evidence of tampering)
- 12V/AUX / USB Outlets (operational)
- Key/Remote (operational)
- Steering Wheel Adjustments (operational)
- Glove Compartment (opens freely, latches securely)
- Center Console/Cup Holder/Storage (operates correctly)
- Exterior Mirrors (adjusts properly, unobstructed view)
- Tag Bracket/Mounting (secures tag, front/rear as applicable)
- Windshield Wiper Functionality (proper operation, speeds, delays)
- Windshield Wiper Blades (cleans windshield, no excessive streaking)
- Windshield Washer (sprays correctly)
- Horn (operational)
- Interior Air Vent (fins intact, properly adjusts)

01/03/2019 11:24 am 1 of 1



Reprint #: 0 DMS Tracking #: 1915611

Form Number: PFF2119 • Rev. Date: 04/2017

CARMAX CERTIFIED INSPECTION REPORT 3 of 4

Meets Standards
 Repaired / Replaced
 N/A

Meets Standards
 Repaired / Replaced
 N/A

MECHANICAL INSPECTION CONT.

Seatbelts and Airbags

- Seatbelts (free of cuts/tears, belt retracts, buckle locks correctly, indicator light illuminates correctly)
- Airbags (no warning indicator lights illuminated, airbag covers free of cuts and tears)

OTHER

- Cruise Control (operational)
- Sunroof (no leaks, no binding while operating)
- Convertible Top (no leaks, no tears, operational)
- Power Door Locks (lock/unlocks applicable doors)
- Power Windows (window regulator/motor/switch operates correctly)
- Power Mirrors (mirror motor/switch operates correctly)
- Power Seats (seat motor/switch operates correctly)
- Heated/Cooled Seats (switch engages heat or AC seats)
- Parking Sensors (operational)
- Rear View Camera (operational)
- Navigation (operational)
- Roof Rack (secured on roof, no rattles present)
- DVD (operates correctly)
- Rear Sunshade (extends and retracts without binding)
- Remote Start (operates with key fob/remote)
- Bluetooth (entertainment/steering wheel controls functioning)
- Memory Seats (able to set preferences)
- Power Sliding Doors (opens and closes correctly)

Certain vehicles may have unrepaired safety recalls. Please check www.nhtsa.gov/recalls to learn if this vehicle has an unrepaired safety recall.